



VoIP Phone snom 300

1. Ethernet cable interference in case the cable shielding is defective

Description

If the Ethernet cable shielding (in case shielding is present) is lose (defective), the display may in some cases show problems.

Serial number: 000413250040 – 000413252750

Workaround

Restart the phone.

Planned fixes

Next hardware revision.